Decompression of B-737 of Aloha Airlines by Separation of Upper Fuselage

April 28th, 1988, near Maui Island, Hawaii

KOBAYASHI, Hideo (Yokohama National University) TERADA, Hiroyuki (Japan Aerospace Technology Foundation)

(Summary)

On April 28th, 1988, a B-737 operated by Aloha Airlines left Hilo, Hawaii Island bound for Honolulu, Oahu. W hen it a pproached the cru ising hei ght of 7, 200m near M aui Isl and, a sudden de compression occurred in the cabin just behind the cockpit. A large part of the cabin structure was lost. A lthough one cabin attendant was sucked out, the aircraft succeeded in making an emergency landing at the airport in Maui, because fortunately one hydraulic system had survived.

1. Component

Fuselage panel structure

2. Event

A B-737-200 operated by Aloha Airlines left Hilo, Hawaii Island bound for Honolulu, Oahu. When it approached the cruising height of 7,200m near Ma ui Island, a sudden decompression occurred at 13:46 local time in the cabin just behind the cockpit. The maximum hoop stress is exerted on the fuselage at the cruising altitude because of the pressure difference between the inside and outside of the cabin is largest.

A part of the cabin structure measuring several meters in length was torn off. One cabin attendant was sucked out of the aircraft and was not found, but the aircraft succeeded in making an emergency landing at the airport in Maui, because fortunately one hydraulic controlling system had survived.

The B-737-200 was an aging aircraft that had been operating for almost nineteen years and suffered from wide spread fatigue damage.

The existence of a crack more than 120 mm in length had been visually recognized by a passenger at the moment of embarkation. The reason why this crack had been overlooked by Aloha Airlines was that they did not conduct the maintenance inspections specified in the manuals because of economic reasons.

3. Course

The a ircraft was fabrica ted in 1969 and had been in service for alm ost nineteen y ears. It had experienced 89,600 flight cycles before the accident. The single lap joint of the fuselage panel structures was manufactured by cold-bond process using scrim cloth and rivets. It was known that the cold-bonded joints have not enough durability in thermal and humid cycle condition. As a matter of course, fastener joints received heavy corrosion damage during 19-years operations. Under the thermal and humidity cycle conditions due to operation, the fuselage structure was subjected to Wide-spread Fatigue Damage (WFD),

including Multiple-Site D amage (MSD). Moreover, the operator has not c onducted the p eriodical inspection and maintenance of the structure required by Regulations even under such deteriorated condition. As a result, the operator overlooked cracks that were long enough to be found visually by passengers.

4. Cause

Direct cause

Unstable propagation of m ultiple site cracks induced by corrosion fatigue took place at the fuse lage panel structure. Because the single lap joint had been manufactured using scrim cloth by the cold bonding process, the scrim cloth and adhesives absorbed water and became brittle over the years of operation.

Indirect cause

Aloha A irlines neg lected to conduct the perio dical maintenance that was specified by M anuals and Regulations. It was just a matter of time that a crack longer than 100 mm that was easily visible from outside the aircraft would occur that was overlooked by the operator.

5. Countermeasure

- (1) In ord er t o prevent the wa ter a bsorption of the b onded joints, which is the main cause of joint degradation, the bonding process was changed from cold bonding to hot bonding.
- (2) The Fe deral Aviation A dministration (FAA) dir ected Aloha Airl ines t o observe the m aintenance manuals strictly in order to maintain the airworthiness of the aircraft.

6. Knowledge

The accident investigation authority revealed that Aloha Airlines had deliberately neglected to conduct the maintenance and inspection in order to reduce operation expenditures. The maintenance manuals and rules are essential for safe operation, so operators should not neglect them for any reason.

7. Background

Because of the company's poor economic condition and high priority given to profits, Aloha Airlines had customarily ignored even the minimum necessary maintenance at the time of the ac cident. Therefore, they overlooked large cracks that even a passenger could visually recognize at the moment of embarkation.

8. Sequel

Until the time of th is acc ident, the F AA had als o been in volved in s upervision of the aircraft manufacturers in reg ard to various items such as design for dura bility and production management of the aircraft besides the primary role of the supervision of aviation safety issues. However, concern was raised after th is acc ident t hat the F AA might not be a ble to provide sufficiently strict supervision t o the manufacturers when critical safety problems occur related t o d esign, manufacture, maintenance, and management of aircraft. Therefore, the policy of the FAA was changed to supervise only items related to safety evaluation and not to commit to items related to design and manufacture.

If a sim ilar incident were to occur in J apan, some people would criticize the responsibility of the regulating government authorities and, opposite to the United States, call for those authorities to be come even more involved in supervising safety design and manufacturing, for unlike. This case is a highly suggestive e xample of h ow much responsibility and authority should be given to g overnment administration.

9. Social Impact

The problems of the structural integrity of aging aircraft became the focus of much interest all over the world. The irresponsible attitude of the airline company regarding the safety management was strongly denounced.

10. Information Source

(1) Aviation Week and Space Technology, vol. 128 (May 16, 1988).

11. Primary Scenario

- 01. Organizational Problems
- 02. Poor Management

03. Poor Work Management

04. Ignorance

05. Insufficient Knowledge

06. Durability of Cold-bonded structure

07. Usage

08. Maintenance/Repair

09. Negligence of Inspection

- 10. Malicious Act
 - 11. Ethics Violation

12. Profit Oriented Policy

13. Usage

14. Transport/Storage

15. Air Transportation

16. Bad Event

17. Chemical Phenomenon

18. Bonded Joint of Composites

19. Material Deterioration

20. Failure

21. Large-Scale Damage

22. Flapping of Fuselage structure

23. Emergency Landing

Failure Knowledge Database / 100 Selected Cases

24. Loss to Organization

25. Social Loss

26. Loss of Credit



Fig. 1 B-737 Made an Emergency Landing with Large-scale Peeling of Fuselage.






Fig. 2 Bonded and Riveted Lap Joint of B-737 Fuselage.








Fig. 4 Fault Tree.